## **PROJECT START**



Figure 1: Site where the Sewage Treatment Package Plant (STP) is to be located. Site viewed from the immediate west



Figure 2: Existing stormwater drainage where the proposed discharged pipeline is to be located

## **GENERAL CONDITIONS OF THE STUDY AREA**



Figure 3: Existing Storm water infrastructure adjacent to the tarred road that is currently not maintained. (Direction - SE)



Figure 5: Existing and degraded Storm water infrastructure with Figure 6: The Metsi Matsho Tributary degraded by Illegal dumping overgrown vegetation (viewed from the south)



Figure 4: The proposed STP area viewed from the southwest. Note the transformed nature of the site



## **ECOLOGY ALONG THE STUDY AREA**




Figure 7: Overview of study site largely transformed and degraded



Figure 9: An example livestock grazing around the proposed site Figure 10: An oxpecker observed lingering around the cow was noted



Figure 8: Remaining vegetation along the proposed discharge pipeline route





Figure 11: An interior view of the site where the proposed Healthcare facility (Clinic) is proposed



Figure 12: Surrounding transformed areas on the vicinity of the study area

## **INFRASTRUCTURE AND SERVICES**



Figure 13: An example of existing electricity powerlines in n close proximity to the site



Figure 16: Water pipelines crossing the Metsi Matsho Tributary



**Figure 14:** Dilapidated sewage pump station noted to be seeping raw sewage directly into the Metsi Matsho tributary



Figure 17: Manholes noted around site seeping sewage directly into the tributary