



REHABILITATION OF BEN MORE DAM



OPTION 2 LAYOUT SENSITIVITY MAP

- Affected Properties
- Eskom Servitude
- Contour Line
- CPlan v3.3**
 - Critical Biodiversity Area
 - Ecological Support Area
- Geology**
 - Granodiorite (Z19)
- Aquatic Specialist Assessment**
 - Riparian Area
 - Seep Wetland
 - 32m Riparian Area Buffer
 - 100m Riparian Area Buffer
 - 500m Riparian Area Buffer

Sources: Chief Surveyor General, ESRI South Africa, Council for Geoscience and Project Team



Projection: WGS_84
 Author: Vukosi Mabunda (August 2021)

GladAfrica House, Hertford Office Park
 90 Bekker Road
 Midrand, 1686
 Tel: 011 312 2537
 Fax: 011 805 1950
 QMF-GE-EV-981A-16/09/2020

- ### Option 2 Layout
- Unaffected Trees
 - Main Discharge Channel
 - New D/S Channel (Invert)

26°5'20"S
 26°5'30"S
 26°5'40"S
 26°5'50"S

28°2'20"E 28°2'30"E 28°2'40"E 28°2'50"E 28°3'0"E