


REHABILITATION OF BENMORE DAM




PREFERRED LAYOUT LOCALITY MAP

- Farm Property
- Eskom Servitude
- Contour Line
- Layout**
- Unaffected Trees
- Weir
- Dam Basin (LB/ Center Berm)
- Dam Wall (NOC) - New C/L
- New 2nd Channel
- Dam Centre Berm - NOC
- Main Discharge Channel
- Dam Basin - 1533 m
- Main Spillway
- Diversion Channel
- Farm Dam - Basin
- New D/S Channel (Invert)
- New NGL level - 1538.5 m

National Freeway; National Route.....	
Arterial Route.....	
Main Road.....	
Secondary Road; Bench Mark.....	
Other Road; Bridge.....	
Track and Hiking Trail.....	
Railway; Station or Siding.....	
Other Railway; Tunnel.....	
Embankment; Cutting.....	
Power Line.....	
Built-up Area (High, Low Density).....	
Buildings; Ruin.....	
Post Office; Police Station; Store.....	
Place of Worship; School; Hotel.....	
Fence; Wall.....	
Windpump; Monument.....	
Communication Tower.....	
Mine Dump; Excavation.....	
Trigonometrical Station; Marine Beacon.....	
Lighthouse and Marine Light.....	
Cemetery; Grave.....	
International Boundary and Beacon.....	
Provincial Boundary.....	
Protected Area.....	
Perennial River.....	
Perennial Water.....	
Non-perennial River.....	
Non-Perennial Water.....	
Dry Water Course.....	
Dry Pan.....	
Marsh and Vlei.....	
Pipeline (above ground).....	
Water Tower; Reservoir; Water Point.....	
Coastal Rocks.....	
Prominent Rock Outcrop.....	
Erosion; Sand.....	
Woodland.....	
Cultivated Land.....	
Orchard or Vineyard.....	
Recreation Ground.....	
Row of Trees.....	

Sources: Chief Surveyor General, ESRI South Africa & Project Team



Projection: WGS_84
Author: Vukosi Mabunda (August 2021)

GladAfrica House, Hertford Office Park
90 Bekker Road
Midrand, 1686
Tel: 011 312 2537
Fax: 011 805 1950
QMF-GE-EV-981A-16/09/2020