

28°2'30"E

28°2'40"E


28°2'50"E

26°5'20"S

26°5'30"S

26°5'40"S

REHABILITATION OF BENMORE DAM




PREFERRED LAYOUT 1:250 000 GEOLOGICAL MAP EAST RAND 2628 MAP SHEET

- Farm Property
- Eskom Servitude
- Contour Line

- Swazian Era**
- Granodiorite (Z19)

- Layout**
- Weir
 - Dam Basin (LB/ Center Berm)
 - Dam Wall (NOC) - New C/L
 - New 2nd Channel
 - Dam Centre Berm - NOC
 - Main Discharge Channel
 - Dam Basin - 1533 m
 - Main Spillway
 - Diversion Channel
 - Farm Dam - Basin
 - New D/S Channel (Invert)
 - New NGL level - 1538.5 m

Sources: Chief Surveyor General, ESRI South Africa, Council for Geoscience and Project Team



Projection: WGS_84
Author: Vukosi Mabunda (August 2021)



GladAfrica House, Hertford Office Park
90 Bekker Road
Midrand, 1686
Tel: 011 312 2537
Fax: 011 805 1950
QMF-GE-EV-981A-16/09/2020

