




REHABILITATION OF BENMORE DAM




OPTION 2 LAYOUT SENSITIVITY LEVELS

- Farm Property
- Eskom Servitude
- Contour Line

- ### Sensitivity Levels
- High (Highly Intact)
 - Medium (Partially Transformed)
 - Low (Highly Transformed)

Sensitivity Levels were assessed based on desktop information and site assessment.

Sources: Chief Surveyor General, ESRI South Africa, Council for Geoscience and Project Team



- ### Option 2 Layout
- Unaffected Trees
 - Main Discharge Channel
 - New D/S Channel (Invert)

Projection: WGS_84
 Author: Vukosi Mabunda (August 2021)

GladAfrica House, Hertford Office Park
 90 Bekker Road
 Midrand, 1686
 Tel: 011 312 2537
 Fax: 011 805 1950
 QMF-GE-EV-981A-16/09/2020